


## 木橋（吊り橋）の補修




20 (R2) 07.04 床板・手摺の腐食が激しく散策に危険な木橋



20 (R2) 08.02 床板の張替え



22 (R4) 04.22 床板の塗装  
約 2 年かけ木橋の補修完成



21 (R3) 12.24 手摺・床横板の取換え



22 (R4) 04.16 木橋の塗装